EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	("4059999").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/27 09:01
L2	2	1 and seal\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 12:07
L3	1	1 and (adhes\$4 bond\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 11:49
L4	2	("5427516").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/27 11:49
L5	1	4 and sleeve	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 14:47
L6	0	4 and (play tolerance)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 12:08
L7	1	4 and (play gap tolerance)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 12:08
L8	370	(73/856).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/11/27 14:46

EAST Search History

			T	T	T	
L9	9	8 and sleeve.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 14:47
L10	4	8 and injection near3 molding.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/11/27 14:48
S1	2	sleeve near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4) near4 play.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 09:16
S2	16	sleeve near8 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4) near6 play.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 09:27
S 3	16	S2 and play.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/11/26 15:19
S4	21045	injection near3 molding.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/27 14:47
S5	5698	S4 and (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 17:57
S6	294705	(injection near3 molding die near2 casting)"." "clm."	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/26 17:57

EAST Search History

S7	5698	S5 and (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 15:21
S8	252	S7 and sleeve.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 18:06
S9	106	S8 and (hole cavity).clm.	US-PGPUB; USPAT; EPO; JPO	OR	OŅ	2007/11/26 18:06
S10	3	S9 and (play tolerance).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 17:28
S11	32	S9 and (play tolerance)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 18:06
S12	23091	(injection near3 molding die near2 casting).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/26 17:57
S13	6190	S12 and (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 17:57
S14	321	S13 and sleeve.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 18:06
S15	140	S14 and (hole cavity).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 18:06
S16	42	S15 and (play tolerance)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/26 18:06
S17	5	S15 and (play tolerance).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/11/27 09:01